

**Inspection/Final Report**

|                            |                           |                               |                  |
|----------------------------|---------------------------|-------------------------------|------------------|
| <b>Client</b>              | : Corrigan Moving Systems | <b>Adjuster</b>               | : Kris Nagy      |
| <b>Adjuster Ph</b>         | : 248.471.4000            | <b>Date</b>                   | : Aug 15, 2023   |
| <b>Order For Service #</b> | : 0611-27520-3            | <b>Received</b>               |                  |
| <b>Valuations</b>          | : Other                   | <b>Estatus Ref #</b>          | : 676213         |
| <b>Shipper</b>             | : <b>Likens</b>           | <b>Admin</b>                  | : Jeff Schatzman |
| <b>Home Ph</b>             | :                         | <b>Additional Information</b> | :                |
| <b>Work Ph</b>             | :                         | <b>Cell Ph</b>                | :                |
| <b>Address</b>             | : NA                      | <b>E-Mail</b>                 | :                |

**Items List**



| #  | Photos  | Item Description          | Condition/ Recommendations/<br>Repairs  | Costs  |
|--|---|---------------------------|---|--|
| <b>SI No:</b> 1<br><b>Inv#:</b> 131<br><b>Wt:</b> 0<br><b>Ctn Avail:</b><br>No | <br>Image1<br><br>Image2<br><br>Image3<br><br>Image4<br><br>Image5<br><br>Image6<br><br>Image7<br><br>Image8<br><br>Image9<br><br>Image10 | Maitland White consoletbl | The console table bottom cross joints for the legs are broken. The driver said they were strapped too tight and they collapsed. There is not enough material left to try to repair. The back lsf leg also bows inward. This appears to be new transit damage.<br>Similar: \$3,680.42<br><a href="https://www.dougfurn.com/maitland-smith-nathan-console-table/8128-34-954/iteminformation.aspx">https://www.dougfurn.com/maitland-smith-nathan-console-table/8128-34-954/iteminformation.aspx</a> | <b>Est:</b> 0.00<br><b>C/S:</b> 0.00<br><b>Fee:</b> 0.00 |



Image11



Image12



Image13



Image14



Image15



Image16



Image17

**SI No:** 2

**Inv#:**

**Wt:** 0

**Ctn Avail:**  
No



Image1



Image2



Image3



Image4



Image5

GE 18 Quart Roaster  
Oven

The top lid on the roaster oven  
is caved in from transit.

Similar: \$90.84

[https://www.amazon.com/NESCO-MWR18-14-Roaster-Quarts-White/dp/B07N9LVXGX/ref=asc\\_df\\_B07N9LVXGX/](https://www.amazon.com/NESCO-MWR18-14-Roaster-Quarts-White/dp/B07N9LVXGX/ref=asc_df_B07N9LVXGX/)

**Est:** 0.00

**C/S:** 90.84

**Fee:** 0.00

**SI No:** 3

**Inv#:**

**Wt:** 0

**Ctn Avail:**  
No



Image1



Image2



Image3



Image4

Chrome Floor lamp

The floor lamp is bent severely  
at the top, the metal has dents  
and the seam has been bent  
and spread out. This appears to  
be new transit damage.

Similar: \$283.00

[https://www.amazon.com/Lite-Source-LS-81699PS-FRO-Torchiere/dp/B008MKC5CQ/ref=asc\\_df\\_B008MKC5CQ/](https://www.amazon.com/Lite-Source-LS-81699PS-FRO-Torchiere/dp/B008MKC5CQ/ref=asc_df_B008MKC5CQ/)

**Est:** 0.00

**C/S:** 283.00

**Fee:** 0.00

**SI No:** 4

**Inv#:** 104

**Wt:** 0




Image2

Drexel Dining Table

The wooden dining table has a  
nickel sized impression mark.

This damaged was noted at  
origin and doesn't appear to be

**Est:** 0.00

**C/S:** 0.00

**Fee:** 0.00

**Ctn Avail:**

Image1

No



Image3

Image4



Image5

Image6



Image7

Image8



Image9

fresh transit damage in our opinion. Not repairable without a 3rd party refinishing the table top which will cost approximately \$1,400.00.

Similar: \$1,050.00

[https://www.1stdibs.com/furniture/tables/dining-room-tables/vintage-drexel-heritage-sketchbook-dining-room-table-banded-burl-wood-parquetry/id-f\\_11708051/](https://www.1stdibs.com/furniture/tables/dining-room-tables/vintage-drexel-heritage-sketchbook-dining-room-table-banded-burl-wood-parquetry/id-f_11708051/)

**SI No:** 5

**Inv#:**

**Wt:** 0

**Ctn Avail:**

No



Image1

Image2



Image3

Image4



Image5

Image6

Royal upright vacuum

The Royal upright vacuum metal hose connection is flared outwards. The shipper tried to bend it back. This appears to be transit damage.

Similar Resale: \$149.95

<https://www.ebay.com/itm/305050916297>

**Est:** 0.00

**C/S:** 149.95

**Fee:** 0.00

**SI No:** 6

**Inv#:** ADD ON

**Wt:** 0

**Ctn Avail:**

No



Image1

Image2



Image3

Image4

40" Proscan TV

The Proscan 40LC45S screen is busted from the center outward. This appears to be transit damage.

Similar: \$299.57

<https://www.amazon.com/Proscan-PLDED4016A-40-Inch-1080p-Full/dp/B00J5L0FMI>

**Est:** 0.00

**C/S:** 299.57

**Fee:** 0.00

|                                   |   |                            |                       |   |           |
|-----------------------------------|---|----------------------------|-----------------------|---|-----------|
| <b>Date of Report</b>             | : |                            | <b>Date Completed</b> | : |           |
| <b>Type of Report</b>             | : | Inspection/Final<br>Report | <b>Expenses</b>       | : | \$ 0.00   |
| <b>Inspection Fee</b>             | : | \$ 225.00                  | <b>Tax</b>            | : | \$ 0.00   |
| <b>Total C/S</b>                  | : | \$ 823.36                  | <b>Total Est</b>      | : | \$ 0.00   |
| <b>Fees</b>                       | : | \$ 0.00                    | <b>Total</b>          | : | \$ 225.00 |
| <b>Additional<br/>information</b> | : |                            |                       |   |           |