

Weathersby Guild Seattle
13701 24th Street East, Unit D6
Sumner, WA 98390
wgs@weathersbyguild.com
Ph: 253-239-3714
Cell: 253-219-4014
Fax: 253-275-2906

Inspection/Final Report

| | | | |
|--------------------|---|-------------------------------|--|
| Client | : Total Military Management | Adjuster | : Nicole Thomason |
| Adjuster Ph | : | Date | : Mar 14, 2017 |
| Received | | Estatus Ref # | : 534288 |
| GBL# | : BGNC0412560 | Admin | : Tim Shaffer |
| Valuations | : FVP | Additional Information | : Repair estimates do not include pickup/delivery fee (if applicable) or sales tax |
| Shipper | : Keymer, Kory | Cell Ph | : |
| Home Ph | : 734-846-3882 | E-Mail | : kkeymer@gmail.com |
| Work Ph | : | | |
| Address | : 2212 Kennewick Place NE Renton, WA 98056 | | |

Items List

| # | Photos | Item Description | Condition/ Recommendations/ Repairs | Costs |
|-------------------|---|-------------------|--|--------------------|
| SI No: 1 | | Dining Room Table | One leg is dented. The edges of the table top are rubbed. | Est: 225.00 |
| Inv#: 026 |   | | | C/S: 0.00 |
| Wt: 0 | Image1 | | | Fee: 0.00 |
| Ctn Avail: | | | Although there is PED noted at origin, the damage claimed appears new. | |
| No | | | | |
| |   | | Shipper is claiming a value of \$800.00 | |
| | Image3 | | | |
| |   | | Repairs can be made on site. | |
| | Image5 | Image6 | | |
| |   | | Estimate to repair: \$225.00 | |
| | Image7 | Image8 | | |
| SI No: 2 | | Beach Bicycle | The pedals and hardware for the front tire are missing. | Est: 0.00 |
| Inv#: 113 |   | | | C/S: 125.00 |
| Wt: 0 | Image1 | Sun C-9 | | Fee: 0.00 |
| Ctn Avail: | | | Damage appears new. | |
| No | | | | |
| |   | | Shipper is claiming a value of | |

| | | |
|---|---|--|
| Image3 | Image4 | \$125.00 |
|  |  | Recommend cash settlement in the amount claimed. |
| Image5 | | |
|  |  | |
| Image7 | Image8 | |
|  |  | |
| Image9 | | |

| | | | | | |
|-------------------|---|---|--------------|--|------------------------------|
| SI No: 3 |  |  | Coffee Table | One handle is broken off and missing. | Est: 260.00 |
| Inv#: 55 | | | | | C/S: 0.00 |
| Wt: 0 | Image1 | Image2 | | Damage appears new. | Fee: 0.00 |
| Ctn Avail: | | | | | |
| No |  |  | | Shipper is claiming a value of \$800.00 | |
| | Image3 | Image4 | | | |
| |  | | | Item can be repaired by replacing handles with similar style round handles, but have not been able to locate a source for "D" style wrought iron handles. | |
| | Image5 | | | | |
| | | | | Similar style, round handles can be obtained from Iron Hardware (http://www.ironhardware.com/products/cabinet/). The sell Heavy Iron Rings (4" x 1/2" solid iron, Iron Oxide) for \$45.00/ea. plus shipping. | |
| | | | | | Estimate to repair: \$260.00 |

| | | | | | |
|-------------------|---|---|----------------------|---|--------------------|
| SI No: 4 |  |  | Webber Genesis Grill | The right side table is dented near the right edge. | Est: 0.00 |
| Inv#: 149 | | | | | C/S: 150.00 |
| Wt: 0 | Image1 | Image2 | Model #: E310 | Damage appears new. | Fee: 0.00 |
| Ctn Avail: | | | | | |
| No |  |  | Serial #: AT 0754471 | Shipper is claiming a value of \$150.00 | |
| | Image3 | Image4 | | | |
| |  |  | | Recommend cash settlement in the amount claimed. | |
| | Image5 | Image6 | | | |



Image7



Image8

SI No: 5**Inv#:** 074**Wt:** 0**Ctn Avail:**

No



Image1



Image2

Haier Kegerator

Model #:
HBF05EBSS

The back left part of the base is dented in and the foot won't reattach.

Est: 0.00**C/S:** 600.00**Fee:** 0.00

Image3



Image4



Image5



Image6

Damage appears new.

Shipper is claiming a value of \$600.00

Replacement parts are not currently available from the manufacturer. The parts that are damaged are not common replaceable parts.

Recommend cash settlement in the amount claimed.

SI No: 6**Inv#:** 319**Wt:** 0**Ctn Avail:**

No



Image1



Image2

F-18 Model

The fuel tank is broken and separated from the model.

Est: 150.00**C/S:** 0.00**Fee:** 0.00

Damage appears new.

Shipper is claiming a value of \$250.00

Estimate to repair: \$150.00

SI No: 7**Inv#:** 30**Wt:** 0**Ctn Avail:**

No



Image1



Image2

King Size
Tempurpedic
Mattress

The carrying handle is torn. The mattress cover is soiled.

Est: 0.00**C/S:** 0.00**Fee:** 0.00

Damage appears new.

Shipper is claiming a value of \$3000.00

Shipper can purchase a new mattress cover from Tempurpedic.com for \$109.00.



Image3



Image4



Image5



Image6



Image7



Image8

Recommend cash settlement in the amount of your discretion







Image9



Image10

| | | | | | |
|-------------------|---|---|-----------------|---|--------------------|
| SI No: 8 |  |  | Nightstand | The top drawer is chipped with wood missing. | Est: 150.00 |
| Inv#: 137 | | | | C/S: 0.00 | |
| Wt: 0 | Image1 | Image2 | | Fee: 0.00 | |
| Ctn Avail: | | | | | |
| No |  | | | | |
| | | | | Damage appears new. | |
| | | | | Shipper is claiming a value of \$200.00 | |
| | | | | Repairs can be made on site. | |
| | | | | Estimate to repair: \$150.00 | |
| SI No: 9 |  |  | Headboard | The top and right side panel are rubbed with white residue and dented. | Est: 150.00 |
| Inv#: 141 | | | | C/S: 0.00 | |
| Wt: 0 | Image1 | Image2 | | Fee: 0.00 | |
| Ctn Avail: | | | | | |
| No |  |  | | | |
| | Image3 | Image4 | | Although there is PED noted at origin, the damage claimed appears new. | |
| | | | | Shipper is claiming a value of \$100.00 | |
| | | | | Repairs can be made on site. | |
| | | | | Estimate to repair: \$150.00 | |
| |  |  | | | |
| | Image5 | Image6 | | | |
| |  |  | | | |
| | Image7 | Image8 | | | |
| |  |  | | | |
| | Image9 | Image10 | | | |
| SI No: 10 |  |  | Footboard | The right top and bottom curved edges are chipped with wood missing. The top surface is scratched and rubbed. | Est: 0.00 |
| Inv#: 142 | | | | C/S: 100.00 | |
| Wt: 0 | Image1 | Image2 | | Fee: 0.00 | |
| Ctn Avail: | | | | | |
| No |  |  | | | |
| | Image3 | Image4 | | Although there is PED noted at origin, the damage claimed appears new. | |
| | | | | Shipper is claiming a value of \$100.00 | |
| | | | | Recommend cash settlement in the amount claimed. | |
| |  |  | | | |
| | Image5 | Image6 | | | |
| |  |  | | | |
| | Image7 | Image8 | | | |
| SI No: 11 | | | Pyrex Measuring | The graduated markings on the | Est: 0.00 |

| | | | | | |
|-------------------|---|---|----------------|--|------------------|
| Inv#: 425 |  |  | Cup Set | outside of the cups are rubbed off. | C/S: 0.00 |
| Wt: 0 | | | | | Fee: 0.00 |
| Ctn Avail: | Image1 | Image2 | | | |
| No | | | | | |
| |  |  | | Damage appears to be consistent with normal wear and tear. | |
| | Image3 | Image4 | | | |
| |  |  | | Shipper is claiming a value of \$20.00 | |
| | Image5 | Image6 | | | |
| | | | | Liability at your discretion. | |

| | | | | | |
|-------------------|---|---|-------------------------|--|-------------------|
| SI No: 12 |  |  | Creative Headset | The microphone is broken off the headset. | Est: 0.00 |
| Inv#: 311 | | | | | C/S: 50.00 |
| Wt: 0 | Image1 | Image2 | | | Fee: 0.00 |
| Ctn Avail: | | | | | |
| No | | | | Damage appears new. | |
| |  |  | | | |
| | Image3 | Image4 | | Shipper is claiming a value of \$50.00 | |
| | | | | | |
| | | | | Recommend cash settlement in the amount claimed. | |

| | | | | | |
|-------------------|---|---|----------------------|---|------------------|
| SI No: 13 |  |  | Bose Speakers | The grill of one speaker is dented. | Est: 0.00 |
| Inv#: 311 | | | | | C/S: 0.00 |
| Wt: 0 | Image1 | Image2 | | | Fee: 0.00 |
| Ctn Avail: | | | | | |
| No | | | | Damage appears new. | |
| |  |  | | | |
| | Image3 | Image4 | | Shipper is claiming a value of \$100.00 | |
| | | | | | |
| | | | | Recommend allowance for loss of appearance. | |

| | | | | | |
|-------------------|---|---|------------------------------|--|--------------------|
| SI No: 14 |  |  | Surfboard Cable Modem | The outer case is cracked and separating. | Est: 0.00 |
| Inv#: 310 | | | | | C/S: 100.00 |
| Wt: 0 | Image1 | Image2 | | | Fee: 0.00 |
| Ctn Avail: | | | | | |
| No | | | | Shipper claims the modem no longer turns on. | |
| |  |  | | | |
| | Image3 | Image4 | | Damage appears new. | |
| | | | | | |
| |  |  | | Shipper is claiming a value of \$100.00 | |
| | Image5 | Image6 | | | |
| | | | | Recommend cash settlement in the amount claimed. | |
| |  | | | | |

| | | | | | |
|-------------------|---|---|---------------------------------|--|------------------|
| SI No: 15 |  |  | Dragon Picture | The glass is chipped in the upper left corner. | Est: 0.00 |
| Inv#: 411 | Image1 | Image2 | | | C/S: 0.00 |
| Wt: 0 | | | | Damage appears new. | Fee: 0.00 |
| Ctn Avail: | | | | | |
| No |  |  | | Shipper is claiming a value of \$100.00 | |
| | Image3 | Image4 | | Amount claimed appears high. | |
| | | | | Recommend cash settlement in the amount of your discretion. | |
| SI No: 16 |  |  | Temperpedic King Cloud Luxe Bed | There is one small area where the mattress cover is soiled. | Est: 0.00 |
| Inv#: 163 | Image1 | Image2 | | | C/S: 0.00 |
| Wt: 0 | | | | Damage appears new. | Fee: 0.00 |
| Ctn Avail: | | | | | |
| No |  |  | | Shipper is claiming a value of \$4500.00 | |
| | Image3 | Image4 | | | |
| |  |  | | Shipper can purchase a replacement zip-on protector cover from Tempurpedic.com for \$199.00-\$250.00 | |
| | Image5 | Image6 | | | |
| |  | | | Recommend cash settlement in the amount of your discretion. | |
| | Image7 | | | | |

Inspection/Final Report

| | | | |
|-------------------------------|--|-----------------------|-------------|
| Date of Report | : Mar 21, 2017 | Date Completed | : |
| Type of Report | : Inspection/Final Report | Expenses | : \$ 0.00 |
| Inspection Fee | : \$ 180.00 | Tax | : \$ 0.00 |
| Total C/S | : \$ 1,125.00 | Total Est | : \$ 935.00 |
| Fees | : \$ 0.00 | Total | : \$ 180.00 |
| Additional information | : Repair estimates DO NOT include any of the taxes or fees noted below: Sales tax: 8.8% (increases to 9.3% on 4/1/17) Estimated shop repair pickup/delivery to this location: \$162.00 | | |