





Preliminary Report

Client	: Suddath Relocation Systems	Adjuster	: SGS Claims
Adjuster Ph	:	Date	: Oct 06, 2023
		Received	
Claim #	: 1454018	Estatus Ref #	: 680026
Valuations	: FVP	Admin	: Jeff Schatzman
Shipper	: Kelly TIMNEY	Additional Information	:
Home Ph	: 814-359-9790	Cell Ph	: 814-359-9790
Work Ph	: 814-359-9790	E-Mail	: KELLY.TIMNEY@GMAIL.COM
Address	: 73 WAHOO LN, OCEANSIDE CA 92058		

Items List

#	Photos	Item Description	Condition/ Recommendations/ Repairs	Costs
SI No: 1 Inv#: 105 Wt: 0 Ctn Avail: No	 Image1	Bowflex Dumbbells	The Bowflex weights are jammed together and won't come out of the base. In our opinion this is not related to transit. \$214.97 https://www.amazon.com/Bowflex-SelectTech-Adjustable-Dumbbells-single/dp/B09LXJCK99/ref=asc_df_B09LXJCK99/	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 2 Inv#: UNK Wt: 0 Ctn Avail: No	 Image1	 Image2 Bookshelf	Two of the bookshelf legs are bent from transit. Similar: \$152.00 https://englishelm.com/products/homeroots-black-four-shelf-metal-standing-book-shelf	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 3 Inv#: UNK Wt: 0 Ctn Avail: No	 Image1	Closet Organizer	The shoe rack is bowed at the middle from transit. Similar: \$36.50 https://www.amazon.com/Whitmor-Stackable-2-Shelf-Storage-Organizer/dp/B07227Q695/ref=asc_df_B07227Q695/	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 4 Inv#: UNK		Plastic Tote	Five plastic totes have cracked lids from transit.	Est: 0.00 C/S: 0.00

Wt: 0 Ctn Avail: No	 Image1	 Image2			Fee: 0.00
	 Image3	 Image4			
	 Image5				
SI No: 5 Inv#: 64 Wt: 0 Ctn Avail: No	 Image1	Shelving Unit	One shelf is missing the end piece from transit. Similar: \$106.99 https://www.walmart.com/ip/6-Tier-Bookshelf-Wood-Bookcase-Open-Storage-Shelf-with-Metal-Frame-Tall-Standing-Display-Rack/2288731804	Est: 0.00 C/S: 0.00 Fee: 0.00	
SI No: 6 Inv#: 25 Wt: 0 Ctn Avail: No		Metal Organizer Basket	The shipper discarded this item prior to the inspection.	Est: 0.00 C/S: 0.00 Fee: 0.00	
SI No: 7 Inv#: UNK Wt: 0 Ctn Avail: No	 Image1	 Image2	Patio Furniture	The wooden bench side support is bent out of the bracket on the right side causing it to be too unstable to sit on. This appears to be new transit damage, not repairable. Similar: \$419.00 https://www.bedbathandbeyond.com/Home-Garden/Sunnydaze-Teak-Outdoor-Patio-Garden-Bench-Mission-Style-2-Person-59-Inch/31953689/product.html	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 8 Inv#: Unknown Wt: 0 Ctn Avail: No		Flat clothing tote	The shipper discarded this item prior to the inspection.	Est: 0.00 C/S: 0.00 Fee: 0.00	

SI No: 9 Inv#: 94 Wt: 0 Ctn Avail: No	 Image1	 Image2	4-Yoga mat holder The yoga mat holder frame is busted on the ends. from transit, not repairable. Similar: \$109.99 https://www.amazon.com/Foam-Roller-Yoga-Mat-Rack/dp/B07HBFHGMZ/ref=asc_df_B07HBFHGMZ/	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 10 Inv#: 127 Wt: 0 Ctn Avail: No	 Image1		Litter Box The back corner of the litter box is cracked from transit.	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 11 Inv#: 99 Wt: 0 Ctn Avail: No	 Image1	 Image2	Dresser Mirror The glass on the dresser mirror is intact but the support beam was ripped out in transit and needs to be repaired. Repairable for \$175.00 Similar: \$139.99 https://www.inhomefurniturewholesale.com/en/product/147770-coaster-furniture-serenity-201974-rectangular-dresser-mirror	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 12 Inv#: 85 Wt: 0 Ctn Avail: No	 Image1	 Image2	Stix Lantern Floor Lamp The floor lamp cord is torn off and the lanterns that go on top of the bulb are cracked. This appears to be new transit damage. Replacement bulb: \$25.99 https://www.amazon.com/OSAL-ADI-Replacement-Square-Frosted-Lampshade/dp/B09VPD2NC1	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 13 Inv#: 8 Wt: 0 Ctn Avail: No	 Image1	 Image2	Escalier Floor Lamp One of the cordage stix is broken which is the piece that holds all the pieces in place. This appears to be new transit damage. Similar: \$250.00 https://www.amazon.com/Adesso-4046-01-Lantern-Outlet-Compatible/dp/B0035492OS/ref=asc_df_B0035492OS/	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 14 Inv#: 69 Wt: 0 Ctn Avail:	 Image1	 Image2	Antique Dictionaries The leather is coming off of the neck and covers of the books. This is age related and inherent vice in our opinion. Similar: \$150.87	Est: 0.00 C/S: 0.00 Fee: 0.00

No	Image1  Image3	Image2		https://www.stevensbooks.com/products/johnson-s-dictionary	
SI No: 15 Inv#: 70 Wt: 0 Ctn Avail: No	Image1  Image3 	Image2  	Book	<p>There's a big crease across the entire bottom part of the large book. This appears to be new transit damage.</p> <p>Retails: \$125.00</p> <p>https://www.bridgepub.com/store/item/images-of-a-lifetime.html</p>	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 16 Inv#: ADD ON Wt: 0 Ctn Avail: No	Image1  Image3 	Image2  	Shadow Box	<p>The wooden frame has come apart on the top LSF corner and is torn on the bottom. This appears to be new transit damage.</p> <p>Similar: \$109.95</p> <p>https://www.bedbathandbeyond.com/Home-Garden/24x36-Shadow-Box-Frame-Light-Brown-Real-Wood-with-a-Navy-Acid-Free/38021463/product.html</p>	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 17 Inv#: ADD ON Wt: 0 Ctn Avail: No	Image1  Image3 	Image2  	Shower Caddy	<p>The shower caddy is missing a foot from transit to put it together.</p> <p>Similar: \$59.95</p> <p>https://www.amazon.com/Toilet-Tree-Products-Stainless-Assembly-Required/dp/B07T577Q4Z/ref=asc_df_B07T577Q4Z/</p>	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 18 Inv#: ADD ON Wt: 0 Ctn Avail: No	Image1  Image3 	Image2  	Bona Mop	<p>The pole on the Bona Mop has a dent in the middle and now the dispenser no longer dispenses. This appears to be new transit damage.</p> <p>\$41.97</p> <p>https://www.amazon.com/Bona-Hardwood-Floor-Spray-Premium/dp/B073HQTZV9/ref=asc_df_B073HQTZV9/</p>	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 19 Inv#: ADD			Kitchen Table	<p>The seams on the legs are slightly separating. This is not</p>	Est: 0.00 C/S: 0.00

ON

Wt: 0

Ctn Avail:
No



Image1



Image2



Image3



Image4

related to transit in our opinion, **Fee:** 0.00
this is wear and age related.

Not repairable.

Similar: \$3750.00

<https://www.chairish.com/product/2242333/vintage-thai-open-mat-top-inlay-dining-table>

Preliminary Report

Date of Report : Oct 06, 2023
Type of Report : Preliminary Report
Inspection Fee : \$ 264.00
Total C/S : \$ 0.00
Fees : \$ 0.00
Additional information :

Date Completed :
Expenses : \$ 0.00
Tax : \$ 0.00
Total Est : \$ 0.00
Total : \$ 264.00