







Preliminary Report

Client	: Suddath Relocation Systems	Adjuster	: SGS Claims
Adjuster Ph	:	Date Received	: Aug 01, 2023
Claim #	: 1437486	Estatus Ref #	: 675160
Valuations	: FVP	Admin	: Jeff Schatzman
Shipper	: NAVIN GURUNG	Additional Information	:
Home Ph	: 720-496-3295	Cell Ph	: 720-335-8190
Work Ph	:	E-Mail	: KNAVIN182@GMAIL.COM
Address	: 111 CENTRE AVE, NEW ROCHELLE NY 10801		

Items List

#	Photos	Item Description	Condition/ Recommendations/ Repairs	Costs
SI No: 1 Inv#: 178 Wt: 0 Ctn Avail: No		Decor	Missing	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 2 Inv#: 262 Wt: 0 Ctn Avail: No		Bed Slots	Missing	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 3 Inv#: 264 Wt: 0 Ctn Avail: No		Head Board	Missing	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 4 Inv#: 268 Wt: 0 Ctn Avail: No		High value item	Missing	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 5 Inv#: 267		Toys and Shoes	Missing	Est: 0.00 C/S: 0.00

Wt: 0 Ctn Avail: No		Fee: 0.00	
SI No: 6 Inv#: 283 Wt: 0 Ctn Avail: No		TV	The Samsung TV doesn't turn on regularly and when it does it just has a line a cross the screen. There is a large scratch on the screen, this appears to be new transit damage. Similar: \$1,097.95 https://www.amazon.com/SAMSUNG-70-Inch-Class-QLED-Built/dp/B08VWD7M67
   Image1 Image2 Image3			Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 7 Inv#: 263 Wt: 0 Ctn Avail: No		Guitar	The bottom panel on the guitar where it plugs in is pulling off, this appears to be new transit damage. Similar: \$299.99 https://www.zzounds.com/item-IBAAEG7M
      Image1 Image2 Image3 Image4 Image5 Image6			Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 8 Inv#: Wt: 0 Ctn Avail: No		PS4	The shipper discarded this item prior to the inspection.
			Est: 0.00 C/S: 0.00 Fee: 0.00

SI No: 9 Inv#: 167 Wt: 0 Ctn Avail: No	table top	Missing	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 10 Inv#: 293 Wt: 0 Ctn Avail: No	     	Kids item The Canon 6D camera won't focus. There is no visible damage or point of impact that would indicate that this is transit related damage, in our opinion this is wear related. Similar: \$1,499.99 https://www.willoughbys.com/Canon_EOS_6D_Mark_II_DSLR_Camera_Body_253204.html	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 11 Inv#: 141 Wt: 0 Ctn Avail: No	Kids chair	Shipper discarded this item prior to the inspection.	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 12 Inv#: 222 Wt: 0 Ctn Avail: No	 	Printer The EPSON printer doesn't work or print at all. There is no visible damage or point of impact that would indicate this occurred in transit, in our opinion this is wear related damage. Similar: \$438.00 https://www.amazon.com/Epson-WorkForce-WF-3640-Wireless-Replenishment/dp/B00JXLGEUC	Est: 0.00 C/S: 0.00 Fee: 0.00




Image3

SI No: 13
Inv#: 281
Wt: 0
Ctn Avail:
No



Image1



Image2

Kitchen Items

The lid on the rice cooker doesn't close due to the latch being broken. This appears to be new transit damage.
Retails: \$364.99
<https://shop.zojirushi.com/products/nphcc>

Est: 0.00
C/S: 0.00
Fee: 0.00



Image3




Image4

SI No: 14
Inv#: 178
Wt: 0
Ctn Avail:
No

Decor

This was not available for inspection at this location.

Est: 0.00
C/S: 0.00
Fee: 0.00

SI No: 15
Inv#: add on
Wt: 0
Ctn Avail:
No




Image1




Image2

front door paint chip

The front door paint is chipped from the movers, this is repairable for \$200.00

Est: 0.00
C/S: 0.00
Fee: 0.00



Image3

Preliminary Report

Date of Report

: Aug 01, 2023

Date Completed

:

Type of Report : Preliminary Report
Inspection Fee : \$ 150.00
Total C/S : \$ 0.00
Fees : \$ 0.00
Additional information : virtual

Expenses : \$ 0.00
Tax : \$ 0.00
Total Est : \$ 0.00
Total : \$ 150.00