Schatzman Enterprises, Inc. dba F.A.S.T.
Post Office Box 8661
Mobile, AL 36689

fastfurniture1@gmail.com Ph: 2517243071

Preliminary Report

Client : Suddath Relocation Systems Adjuster : SGS Claims

Adjuster Ph : Date : Aug 01, 2023

Received

Valuations : FVP **Admin** : Jeff Schatzman

Shipper : NAVIN GURUNG Additional

Information

Work Ph : E-Mail : KNAVIN182@GMAIL.COM

Address : 111 CENTRE AVE, NEW

ROCHELLE NY 10801

Items List

#	Photos	Item Description	Condition/ Recommendations/ Repairs	Costs
SI No: 1		Decor	Missing	Est: 0.00
Inv#: 178				C/S: 0.00
Wt: 0				Fee: 0.00
Ctn Avail: No				
SI No: 2		Bed Slots	Missing	Est: 0.00
Inv#: 262				C/S: 0.00
Wt: 0				Fee: 0.00
Ctn Avail: No				
SI No: 3		Head Board	Missing	Est: 0.00
Inv#: 264				C/S: 0.00
Wt: 0				Fee: 0.00
Ctn Avail: No				
SI No: 4		High value item	Missing	Est: 0.00
Inv#: 268				C/S: 0.00
Wt: 0				Fee: 0.00
Ctn Avail: No				
SI No: 5		Toys and Shoes	Missing	Est: 0.00
Inv#: 267				C/S: 0.00

Wt: 0 Fee: 0.00 Ctn Avail: No **SI No:** 6 TV The Samsung TV doesn't turn **Est:** 0.00 on regularly and when it does it C/S: 0.00**Inv#:** 283 just has a line a cross the **Wt:** 0 Fee: 0.00 screen. There is a large scratch Ctn Avail: on the screen, this appears to No be new transit damage. Similar: \$1,097.95 https://www.amazon.com/SAMS Image1 Image2 UNG-70-Inch-Class-QLED-Built/dp/B08VWD7M67 Image3 **SI No:** 7 Guitar The bottom panel on the guitar **Est:** 0.00 where it plugs in is pulling off, Inv#: 263 **C/S:** 0.00 this appears to be new transit **Wt:** 0 **Fee:** 0.00 damage. Ctn Avail: Similar: \$299.99 Nο https://www.zzounds.com/item--IBAAEG7M Image1 Image2











PS4

SI No: 8 Inv#:

Ctn Avail:

No

Wt: 0

The shipper discarded this item **Est:** 0.00

prior to the inspection.

C/S: 0.00

Fee: 0.00

SI No: 9 Missing **Est:** 0.00 table top Inv#: 167 C/S: 0.00 Wt: 0 Fee: 0.00 Ctn Avail: No **SI No:** 10 Kids item The Canon 6D camera won't **Est:** 0.00 focus. There is no visible Inv#: 293 **C/S:** 0.00 damage or point of impact that **Wt:** 0 **Fee:** 0.00 would indicate that this is Ctn Avail: transit related damage, in our No opinion this is wear related. Similar: \$1,499.99 https://www.willoughbys.com/C Image2 anon EOS 6D Mark II DSLR Ca mera_Body_253204.html Image3 Image4 Image5 Image6 **SI No:** 11 Kids chair Shipper discarded this item **Est:** 0.00 prior to the inspection. Inv#: 141 C/S: 0.00 **Wt:** 0 Fee: 0.00 Ctn Avail: No **SI No:** 12 Printer The EPSON printer doesn't work **Est:** 0.00 or print at all. There is no Inv#: 222 C/S: 0.00 visible damage or point of **Wt:** 0 Fee: 0.00

Ctn Avail: No



Image1 Image2 impact that would indicate this occurred in transit, in our

damage.

Similar: \$438.00

https://www.amazon.com/Epso

n-WorkForce-WF-3640-

opinion this is wear related

Wireless-

Replenishment/dp/B00JXLGEUC



Image3

SI No: 13 Inv#: 281 **Wt:** 0

Ctn Avail:

No





Image2



Kitchen Items

The lid on the rice cooker doesn't close due to the latch being broken. This appears to be new transit damage.

Retails: \$364.99

https://shop.zojirushi.com/prod

ucts/nphcc





Image3

Image4

Decor

This was not available for **Est:** 0.00 inspection at this location. C/S: 0.00

Fee: 0.00

Est: 0.00

C/S: 0.00

Fee: 0.00

Ctn Avail:

SI No: 14

Inv#: 178

No

Wt: 0

SI No: 15 Inv#: add

on **Wt:** 0

Ctn Avail: No



Image1



Image2



Image3

front door paint chip The front door paint is chipped **Est:** 0.00 from the movers, this is **C/S:** 0.00 repairable for \$200.00 Fee: 0.00

Preliminary Report

Date of Report Date Completed : Aug 01, 2023 : Type of Report : Preliminary Report **Expenses** : \$ 0.00 Inspection Fee **:** \$ 150.00 Tax : \$ 0.00 Total C/S : \$ 0.00 **Total Est** : \$ 0.00 Fees : \$ 0.00 **Total :** \$ 150.00

Additional : virtual

information