

Inspection/Final Report

Client	: Eagle Claims Services	Adjuster	: MADDOX MAGRINO
Adjuster Ph	:	Date	: Apr 18, 2024
Claim #	: 38-0185-24	Received	
Valuations	: FVP	Estatus Ref #	: 689287
Shipper	: Mark McGuire	Admin	: Karl Eulberg
Home Ph	:	Additional Information	:
Work Ph	:	Cell Ph	: 619-565-4096
Address	: 1390 Santa Alicia Ave Apt 16307 Chula Vista, CA 91913	E-Mail	: mark.mcguire.ca@gmail.com

Items List

#	Photos	Item Description	Condition/ Recommendations/ Repairs	Costs
SI No: 4 Inv#: 35 Wt: 0 Ctn Avail: No	 Image1  Image2  Image3	Lane Home Furnishings Reclining Sofa	Shipper claims parts of sofa and love were switched causing misalignment. Condition appears to be new and transit related. Estimate to disassemble sofa and loveseat and re-install correctly: \$600 Two technicians required.	Est: 600.00 C/S: 0.00 Fee: 0.00
SI No: 5 Inv#: 12 Wt: 0 Ctn Avail: No	 Image1  Image2  Image3	Wooden Lane Home Furnishings Headboard	Top right and left corners are rubbed and dented. Damage appears to be new and transit related. Estimate to repair \$219	Est: 219.00 C/S: 0.00 Fee: 0.00

SI No: 6 Inv#: 13 Wt: 0 Ctn Avail: No	 Image1  Image2  Image3	Lane Home Furnishings Footboard	Chipper along top rail. Damage appears to be new and transit related. Estimate to repair \$180	Est: 180.00 C/S: 0.00 Fee: 0.00
SI No: 7 Inv#: 18 Wt: 0 Ctn Avail: No	 Image1  Image2	Wooden Lane Home Furnishings Nightstand	Right side panel is dented with paint transfer. Damage appears to be new and transit related. Estimate to repair \$219	Est: 219.00 C/S: 0.00 Fee: 0.00
SI No: 8 Inv#: 77 Wt: 0 Ctn Avail: No	 Image1  Image2  Image3	ARKMat Horse Stall Mat	Shipper claims item was rolled up for shipment and split. Image 2 is shipper-supplied photo of item as packaged. Damage appears to be new and transit related. Recommend cash settlement in the amount claimed.	Est: 0.00 C/S: 125.00 Fee: 0.00
SI No: 9 Inv#: 110 Wt: 0 Ctn Avail: No	 Image1  Image2  Image3  Image4  Image5  Image6	Rogue 25Lb Weights (x3)	Shipper claims items were dropped at destination. Dented and scratched with paint transfer. Damage appears to be new and transit related. Unable to repair to professional standards. Recommend cash settlement in the amount claimed.	Est: 0.00 C/S: 219.00 Fee: 0.00
SI No: 10 Inv#: 48 Wt: 0 Ctn Avail: No	 Image1  Image2	Painting w/ Float Canvas Frame 64" x 30"	Frame chipped on right side center and lower left sides. Damage appears to be new and transit related. Estimate to repair \$319	Est: 319.00 C/S: 0.00 Fee: 0.00



Image3 Image4

SI No: 10

Inv#:

Wt: 0

Ctn Avail:

No



Image1



Image2



Image3



Image4

Rouge weight rack
Monster Lite

**** ADD-ON ITEM ****

Est: 0.00

C/S: 125.00

Fee: 0.00

Missing one of two bars for pin and pipe safety set.

Parts missing are likely transit related.

Recommend cash settlement for value of like kind and quality replacement.

Rougefitness.com

MONSTER PIN AND PIPE SAFETY SETS
(pair)

43"

\$125

SI No: 11

Inv#:

Wt: 0

Ctn Avail:

No



Image1



Image2

Electric stand up desk 30" x 60"
Bamboo

Shipper claims item is missing legs and assembly hardware.

Est: 0.00

C/S: 643.00

Fee: 0.00

Parts missing are likely transit related.

Cost to source and return to replace missing parts exceeds amount claimed.

Claimant-supplied proof of value attached as image 2.

Recommend cash settlement in amount claimed.

SI No: 12

Inv#:

Wt: 0

Ctn Avail:

No



Image1



Image2

Dresser

**** ADD-ON ITEM ****

Est: 320.00

C/S: 0.00

Fee: 0.00

Left side scraped and dented.

Damage appears to be new and transit related.

Estimate to repair \$320

SI No: 13

Inv#:

Dining table

Shipper claims table was delivered missing two of four

Est: 0.00

C/S: 0.00

Wt: 0			legs and all assembly hardware.	Fee: 0.00
Ctn Avail: No			Item was discarded by shipper prior to inspection.	
SI No: 14			Vizio Soundbar Model: SB3851-D0	Est: 0.00
Inv#: 106			Cover material is torn near top left corner of controls.	C/S: 0.00
Wt: 0	Image1	Image2	Item operates properly.	Fee: 0.00
Ctn Avail: No			Possible transit related damage.	
	Image3	Image4	Recommend allowance for loss of appearance/function.	
			\$40	
SI No: 15			Vizio TV 50" Model: E50-C1	Est: 0.00
Inv#: 69			Display panel has color streaks along top down to center of display.	C/S: 229.00
Wt: 0	Image1	Image2	Damage appears to be new and transit related.	Fee: 0.00
Ctn Avail: No			Item no longer offered for sale as new item.	
	Image3	Image4	Recommend cash settlement in the amount claimed.	
				
	Image5	Image6		

Inspection/Final Report

Date of Report	: Apr 18, 2024	Date Completed	:
Type of Report	: Inspection/Final Report	Expenses	: \$ 0.00
Inspection Fee	: \$ 265.00	Tax	: \$ 0.00
Total C/S	: \$ 1,341.00	Total Est	: \$ 1,857.00
Fees	: \$ 0.00	Total	: \$ 265.00
Additional information	:		