

Inspection/Final Report

Client	: SIRVA Worldwide Relocation & Moving	Adjuster	: Jeanne DuMont
Adjuster Ph	: 260 429 3167	Date Received	: Jul 31, 2023
Claim #	: 10766-3	Estatus Ref #	: 675130
Valuations	: Other	Admin	: Rich Culp
Shipper	: Kristina Norderhaug	Additional Information	:
Home Ph	:	Cell Ph	:
Work Ph	:	E-Mail	:
Address	: NA		

Items List


#	Photos	Item Description	Condition/ Recommendations/ Repairs	Costs
Sign				
SI No: 1 Inv#: Wt: 0 Ctn Avail: No	 Image1	 Image2	Rail/Headboard/Etc (3) Bed support rails missing support legs. (1) Support rail is missing the hardware to attach support leg. Repairs completed. August 31, 2023	Est: 0.00 C/S: 0.00 Fee: 0.00
	 Image3	 Image4		
	 Image5	 Image6		
	 Image7	 Image8		
	 Image9			

Image9



SI No: 2

Inv#:

Wt: 0

Ctn Avail:

No



Image1



Image2

Plasma/Flat Screen
TV

Est: 0.00

C/S: 0.00

Fee: 0.00



Image3



Image4



Image5



Image6

SI No: 3

Inv#:

Wt: 0

Ctn Avail:

No



Image1



Image2

Recliner

Est: 0.00

C/S: 0.00

Fee: 0.00



Image3




Image4




Image5




Image6



SI No: 4

Inv#:

Wt: 0

Ctn Avail:

No



Image1



Image2

Display Cases -
Large

Est: 0.00

C/S: 0.00

Fee: 0.00



Image3



Image4

SI No: 5

Inv#:

Wt: 0




Image2

Display Cases -
Large

Est: 0.00

C/S: 0.00

Fee: 0.00

Ctn Avail: Image1

No



Image3



Image4

SI No: 6

Inv#:

Wt: 0

Ctn Avail:

No



Image1



Image2

Bicycle

Est: 0.00

C/S: 0.00

Fee: 0.00



Image3



Image4



Image5

SI No: 7

Inv#:

Wt: 0

Ctn Avail:

No



Image1



Image2

Pool Table

Est: 0.00

C/S: 0.00

Fee: 0.00



Image3



Image4



Image5



Image6



Image7




Image8



Image9



Image10



Image11




Image12



Image13

SI No: 8

Carpet Cleaner

The shipper discarded this item prior to the inspection.

Est: 0.00

Inv#: 351

C/S: 0.00


Wt: 0

Fee: 0.00

Ctn Avail:

No

SI No: 9



Gun/Accessory

Missing. Photo from shipper.

Est: 0.00

Inv#:

C/S: 0.00

Wt: 0

Fee: 0.00

Ctn Avail:

No

Image1

SI No: 10



Dining Room Chair

Est: 0.00

Inv#:

C/S: 0.00

Wt: 0

Fee: 0.00

Ctn Avail:

No

Image1

Image2



Image3



Image4



Image5



Signature

The signature below is for customer acceptance of all repairs that are designated by "Accepted" on each repaired item.

KMO

Inspection/Final Report

Date of Report	:		Date Completed	:	
Type of Report	:	Inspection/Final Report	Expenses	:	\$ 0.00
Inspection Fee	:	\$ 0.00	Tax	:	\$ 0.00
Total C/S	:	\$ 0.00	Total Est	:	\$ 0.00
Fees	:	\$ 0.00	Total	:	\$ 0.00
Additional information	:	PHOTOS			